

Northern Railway

Headquarters Office,  
Baroda House,  
New Delhi- 110001.

No.230-Elect/TRS/202/Operational Circular

Dated: 19.09.2023

Sr. Divnl Elect. Engineer/RSO  
Northern Railway  
D.R.M. Office  
Delhi, Lucknow, Ambala & Moradabad.

Sr. Divnl Elect. Engineer/TRD  
Northern Railway  
D.R.M. Office  
Firozpur

**Sub:** Action after cattle run over (CRO) cases to prevent unsafe working and detention.

**Ref:** NRHQ Operational Circular No. 017, dated 28.07.2022.

In reference to para "C(1)" of OC-017, the line "These shall be replaced even if these are observed normal. Pipes removed be marked defective or torned to avoid re-use" to be read as "If CRO marks are noticed in surrounding area of BP/FP rubber pipes, Maintenance staff will replace BP/FP rubber pipes. Removed pipes shall be torned/cut in to two pieces to avoid re-use". Other instructions contained in Operational Circular will remain unchanged.

Please ensure strict compliance.



(Deepak Grewal)  
Chief Electrical Loco Engineer