### NORTHERN RAILWAY

**DRM** Office S.E.Road, New Delhi

No.10-T/SD/12/2024/Safety

Dated: 02.04.2025

All Concerned Branch Officers,

NR, DLI Division.

Divisional Safety Drive No. 12/2025

Sub:- 15 days Special Safety Drive on Precautions during loading and unloading..

Ref: (ii). PCSO L.No. 81-T/SD/07/2025/SAFETY dated 01.04.2025

(ii) RB Letter no . 2025/Safety-I/3/4 Dated. 28.03.2025.

(iii) RB Letter no of even No. dated 11.03.2025.

A special safety drive of 15 days to be launched from 01.04.2025 to 15.04.25 covering all loading &unloading points for the following aspects involving all loading & unloading points.

To ensure even loading of wagons ١.

Prescribed loading pattern/diagram to be followed during loading II.

To confirm complete unloading of wagons. III.

- Release Memo to be given after ensuring complete unloading of wagons. IV.
- CCTVS to be placed at proper position to record loading/unloading pattern. ٧.

After loading/unloading, doors of all wagons should be closed. VI.

Rotation of the tippler to be checked as per the extant norms. VII.

Precautions to be taken during loading/unloading of Ballast DMT/BOBYN: VIII.

a) Ensuring even loading of hoppers before handing over load.

- b) Ensuring opening of doors before unloading and avoiding unloading of wagons with defective doors.
- c) Check for track clearance before movement of loaded & empty Ballast rakes.

d) Marking of BOBYNs with defective doors.

e) Detachment of/ attention to wagons with defective doors.

It should be ensured that all Loading & Unloading points are covered.

Officers of departments from DLI Division should also be involved, effective follow up action should be taken on all deficiencies and irregularities during the drive. Daily report Division/loading & unloading point) should be sent to this office and must be uploaded in the google sheet https://docs.google.com/spreadsheets/d/1pfU6fGnhheldgip-HN8pQzSNXZII1-LbQuujaJCyObo/edit?usp=sharing by 9:00 AM. Concerned BO's to critically analyze such cases and ensure effective actions are taken as per rule. Action taken should be sent to this office by 16.04.2025 for further submission to HQ Office

Performa/format of report to be submitted is enclosed as below:

Sr Stat	Divisi on	Tota I Ioadi	Total loadi	% of loadi	Total unlo adin	Total unlo adin	% of unloa	Major abnorma lities	Major abnorma lities	Total no of deficien	Total no of deficien
to	N	ng poin ts	ng point s audit ed	point s audit ed	g point s	g point s audit	points audite d	found	attended	cies found	cies attende d

Sr. Divisional Safety Officer S.E. Road, DRM Office New Delhi

Copy:-

1. DRM/DLI---

please.

2. ADRM/infra, ADRM/admin, ADRM/OP --- please.

For Kind information

For kind information

### NORTHERN RAILWAY

HEAD QUARTER OFFICE BARODA HOUSE NEW DELHI

DATED 01.04.2025

NO.81-T/SD/07/2025/SAFETY

DIVL. RAILWAY MANAGER DRM'S OFFICE DLI, LKO, MB, FZR, UMB & JAT

## SAFETY DRIVE NO. - 07/2025 (RB-01)

Sub: 15 days Special Safety Drive on Precautions during loading and unloading.

Ref: Railway Board letter no. 2025/Safety-I/3/4 Dated. 28.03.2025

A special safety drive of 15 days to be launched from 01.04.2025 covering all loading & unloading points for the following aspects involving all loading & unloading points.

- 1. To ensure even loading of wagons
- II. Prescribed loading pattern/diagram to be followed during loading
- III. To confirm complete unloading of wagons.
- IV. Release Memo to be given after ensuring complete unloading of wagons.
- V. CCTVS to be placed at proper position to record loading/unloading pattern.
- VI. After loading/unloading, doors of all wagons should be closed.
- VII. Rotation of the tippler to be checked as per the extant norms.
- VIII. Precautions to be taken during loading/unloading of Ballast DMT/BOBYN:
  - a) Ensuring even loading of hoppers before handing over load.
  - b) Ensuring opening of doors before unloading and avoiding unloading of wagons with defective doors.
  - c) Check for track clearance before movement of loaded & empty Ballast rakes.
  - d) Marking of BOBYNs with defective doors.
  - e) Detachment of/ attention to wagons with defective doors.

It should be ensured that all Loading & Unloading points are covered.

Officers of departments from HQ should also be involved, effective follow up action should be taken on all deficiencies and irregularities during the drive. Daily report Division/loading & unloading point) should be sent to this office or must be uploaded in the google sheet <a href="https://docs.google.com/spreadsheets/d/1pfU6fGnhheldgip-HN8pQzSNXZII1-LbQuujaJCyObo/edit?usp=sharing">https://docs.google.com/spreadsheets/d/1pfU6fGnhheldgip-HN8pQzSNXZII1-LbQuujaJCyObo/edit?usp=sharing</a> by 9:00 AM. Sr. DSOs to critically analyze such cases and

ensure effective actions are taken as per rule. Action taken should be sent to this office by 17.04.2025. Apart from sending hard copy, the report should invariably be uploaded in SMDMS, both in PDF & DOC format and may also be emailed at <a href="mailto:dycsonrelec@gmail.com">dycsonrelec@gmail.com</a> positively for further submission to Rly Board.

Performa/format of report to be submitted is enclosed as below:

#### Annexure

0.	Status up to	Division	Total loading points	Total loading points audited	% of loading points audited	Total unloadi ng points	Total unloadi ng points audited	% of unloadin g points audited	Major abnormalities found	Major abnormalities attended	Total no of deficiencies found	Total no of deficiencies attended
	-			-			duartes					

Dy. CSO/ Waffie/HQD (-Y-) (For Principal Chief Safety Officer)

#### Copy to:

- 1. Secy. to GM for kind information of GM.
- 2. Secy. to AGM for kind information of AGM.
- 3. PCME, PCEE, PCE, PCSTE and PCOM for information and necessary action please.
- 4. Sr. DSO/DLI, FZR, UMB, MB, LKO, JAT for information and necessary action please.



# भारत सरकार(GOVERNMENT OF INDIA) रेल मंत्रालय(MINISTRY OF RAILWAYS ) रेलवे बोर्ड(RAILWAY BOARD)



क्र. 2025/संरक्षा-।/3/4

नई दिम्सी, दिनांक: 28.03.2025

महाप्रबंधक, सभी क्षेत्रीय रेलवे, और प्रबंध निदेशक, के.आर.सी.एस और डी.एफ.सी.सी.आई.एस.

> विषय: Drive no.1 (FY 2025-26) : Special Drive on Precautions during Loading & Unloading

A special Safety Drive of 15 days is to be launched from 01.04.2025 covering all Loading & Unloading points for the following aspects involving all loading & unloading points.

- To ensure even loading of wagons.
- Prescribed loading pattern/diagram to be followed during loading.
- III. To confirm complete unloading of wagons.
- IV. Release Memo to be given after ensuring complete unloading of wagons.
- V. CCTVs to be placed at proper position to record loading/unloading pattern.
- VI. After loading/unloading, doors of all wagons should be closed.
- VII. Rotation of the tippler to be checked as per the extant norms.
- VIII. Precautions to be taken during loading/unloading of Ballast DMT/BOBYN:
  - a) Ensuring even loading of hoppers before handing over load.
  - b) Ensuring opening of doors before unloading and avoiding unloading of wagons with defective doors.
  - c) Check for track clearance before movement of loaded & empty Ballast rakes.
  - d) Marking of BOBYNs with defective doors.
  - e) Detachment of/ attention to wagons with defective doors.

It should be ensured that all Loading & Unloading points are covered

Officers of departments from HQ should also be involved, Effective follow-up actions should be taken on all deficiencies and irregularities noticed during the drive. Daily report (Division/loading & unloading point) should be sent to Railway Board by 9.00 am. PCSOs to critically analyze such cases and ensure effective actions are taken as per rule. Action taken should be sent to the Board by 20.04.2025. Apart from sending hard copy, the report should invariably be uploaded on SMDMS, both in PDF and DOC format and may also be e-mailed at <a href="mailto:edeesafety@gmail.com">edeesafety@gmail.com</a> and <a href="mailto:safetyimp46@gmail.com">safetyimp46@gmail.com</a>. Performa/format of report to be submitted is enclosed as below.

**Annexure** 

S. N	Sta tus up to	Zo ne	Divi sion	Tot al loa din g poi nts	Total Load ing poin ts audi ted	% of Loa ding poin ts audi ted	Total unloa ding point s	Total unloa ding point s audit ed	% of unloading point saudited	Major abnor malitie s found	Major abnor malitie s attende d	Total no of defici encies found	Total no of defici encies attend ed
											and the second s	The state of the s	and the financial and an analysis of the second

(Ashok Kumar Nakra)

अशोक कुमार नाकरा

Executive Director/EE/Safety कार्यकारी निदेशक/ई.ई./संरक्षा