मण्डल कार्यालय नई दिल्ली

तकनीकी सर्कुलर - 03/2025

विषय :- न्यूट्रल सेक्शन पर VCB खोलने और बंद करने के संबंध में। सन्दर्भ :- NRHQ Letter no -230-Elect/TRS/RSO dated 23.04.25

विगत समय में DFCCIL सेक्शन पर गाडी संचालन के दौरान कुछ चालक दल द्वारा न्यूट्रल सेक्शन पर DJ/VCB को ओपन नहीं किया गया जिसके परिणामस्वरूप PTFE/न्यूट्रल सेक्शन पर heavy flashing हुई । उक्त घटनाओं/फेलियर के कारण DFCCIL में ट्रेन संचालन बाधित रहा | •

अत: इस सम्बन्ध में मंडल के सभी CLIs को निर्देशित किया जाता है कि वे अपने—अपने नामित/गैर-नामित चालक दल को काउन्सलिंग करें कि DFCCIL में गाडी संचालन के दौरान न्यूट्रल सेक्शन से पहले स्थित सभी निर्देशित बोर्डों (500 मीटर, 250 मीटर, DJ open तथा DJ close बोर्ड) का नियमानुसार अनुपालन करते हुए पर्याप्त दूरी से लोकोमोटिव के DJ/VCB को ओपन /क्लोज अवश्य करें, सुरक्षित एवं संरक्षित रेल परिचालन सुनिश्चित किया जा सकें | सभी CLIs अपनी काउन्सलिंग रिपोट दिनांक 04.06.25 को मण्डल कार्यालय में अविलम्ब प्रस्तुत करें।

नोट :- सभी LP/ALPs उक्त निर्देशों का DFCCIL के साथ-साथ IR के भी सभी सेक्शन पर गाडी कार्य करते समय सभी निर्देशित बोर्डों का अनुपालन करते हुए लोकोमोटिव का DJ / VCB ओपन /क्लोज करें |

> वरिष्ठ मण्डल विद्युत अभियंता / परिचालन उत्तर रेलवे, नई दिल्ली

प्रतिलिपि :--

- मण्डल रेल प्रबंधक / मण्डल कार्यालय / नई दिल्ली / उत्तर रेलवे सूचनार्थ ।
- मुख्य विद्युत अभियंता / परिचालन / उत्तर रेलवे, बड़ौदा हाऊस, नई दिल्ली सूचनार्थ।
- अपर मण्डल रेल प्रबंधक /पिरचालन / नई दिल्ली / उत्तर रेलवे—सूचनार्थ ।
- मुख्य विद्युत लोको अभियंता / उत्तर रेलवे, बड़ौदा हाऊस, नई दिल्ली— सूचनार्थ।
- वरिष्ठ मण्डल सुरक्षा अधिकारी / मण्डल कार्यालय / नई दिल्ली / उत्तर रेलवे-सूचनार्थ।
- विरष्ठ मण्डल राजभाषा अधिकारी / मण्डल कार्यालय / नई दिल्ली / उत्तर रेलवे-सूचनार्थ।
- प्रधानाचार्य प्रशिक्षण केन्द्र —गाजियाबाद / तुगलकाबाद / उत्तर रेलवे—आवश्यक कार्यवाही हेतु।
- समस्त लोको लॉबी नोटिस बोर्ड- आवश्यक कार्यवाही हेतु।
- समस्त मुख्य लोको निरीक्षक ;दिल्ली मण्डल आवश्यक कार्यवाही हेतु।
- बेसिक प्रशिक्षण केन्द्र / तुगलकाबाद / उत्तर रेलवे—आवश्यक कार्यवाही हेतु।

Northern Rallway

Headquarters Office, Baroda House, New Delhi

No. 230-Elect/TRS/112.

Dated 23.04.2025

Sr.Div. Elect. Engg/RSO, Northern Railway, DRM Office, Delhi, Firozpur, Lucknow, Moradabad & Ambala Sr.Div. Elect, Engg/Tr. Northern Railway, DRM Office, Jammu Tawi.

Sub: Counseling of loco pilots for opening and closing of VCB at neutral section.

Ref: CGM/DFCCIL/Tundla letter No. DFCCIL/EL/TDL/Gen Corre/25-03/08, dated

13.03.25

Vide letter under reference above, DFCCIL has mentioned that there are cases of not opening of DJ switch on neutral section by loco pilots which caused heavy flashing at PTFE/neutral section.

In view of the above, it is requested to ensure that all running staff, especially loco pilots operating on sections interfacing with DFCCIL, are counseled thoroughly on this aspect.

(Kamal Kant Rastogi)

Dy. Chief Electrica Dengineel/Operation.

Copy to: PCEE, CEE/OP & CELE - for kind information please.



डेडीकेटेड फ्रेट कोरीडोर कॉर्पोरेशनऑफ इंडिया लि.

भारत सरकार (रेल मंत्रालय) का उपक्रम

Dedicated Freight Corridor Corporation Of India Limited

A Govt. of India (Ministry of Railways) Enterprise

No. DFCCIL/EL/TDL/Gen Corre/25-03/08

Date: - 13.03.2025

DRM PRYJ

Subject: Regarding counselling of LP/APL for Opening and Closing of DJ switch of Loco.

Ref: DFCCIL/EL/TDL/Gen Corre/25-01/12 dated:22.01.2025

Vide reference above, it was requested for counselling of LP/ALP for opening of DJ Switch of loco before approaching the Neutral Section.

The same case of not opening of DJ switch has occurred on **11.03.2025** when Loco Pilot of Train No-SOG, Loco No-38064/BJU did not open the DJ Switch timely causing heavy flashing occurred at the PTFE of Umari TSS of DFCCIL. Loco pilot has accepted his fault in his statement. The same is attached.

In view of the above, it is kindly requested to look into the matter and arrange counselling of ALP/LPs regularly, regarding the importance of Opening of DJ Switch before approaching the Neutral Section at SP and TSS locations. This small but crucial action can enhance the reliability of the system and avoid any further breakdown on account of Panto entanglement.

DA: - as above

(Prafull Chandra Panday) Chief General Manager DFCCIL/Tundla

Copy to: -

- 1. **CEDE/NCR:** for kind information please.
- 2. CELE/NCR: for kind information please.
- 3. **GM/EL/EC-I/HQ:** for kind information please.
- 4. GM/OP&BD/HQ: for kind information please.
- 5. Dy. CPM/EL/TDL: for kind information and necessary action please.



डेडीकेटेड फ्रेट कोरीडोर कॉर्पोरेशनऑफ इंडिया लि.

भारत सरकार (रेल मंत्रालय) का उपक्रम

Dedicated Freight Corridor Corporation Of India Limited

A Govt. of India (Ministry of Railways) Enterprise

No. DFCCIL/EL/TDL/Gen Corre/25-01/12

Date: - 22.01.2025

DRM DLI, DRM UMB, DRM MB, DRM AGC, DRM KTT, DRM PRYJ,

Sub.: - Regarding Counselling of LP/ALP for Opening and Closing of DJ switch of

Some cases of heavy flashing at PTFE/Neural section resulting in breaking of PTFE Rod and Panto entanglement, have been reported in BPUN-KRJN section of EDFC.

After analyzing the cases, it has been found that some of the LP/ALPs are not opening the DJ switch before approaching the Neutral Section. It causes the above failures thereby disrupting the traffic movement for more than 3 to 4 hours resulting in huge revenue losses.

In view of the above, it is kindly requested to look into the matter and arrange counselling of ALP/LPs regarding the importance of Opening of DJ Switch before approaching the Neutral section at SP and TSS locations. This small but crucial action can enhance the reliability of the system and avoid any further breakdown on account of Panto entanglement.

> (Prafull Chandra Pandey) Chief General Manager DFCCIL/Tundla

Copy to: -

- 1. GM/EL/EC-I/HQ: for kind information please.
- 2. GM/OP&BD/HQ: for kind information please.
- Dy. CPM/EL/TDL: for kind information and necessary action please.

Occ Prys

श्रीमान भेड़ा हम

LPG!- FARTH LINN
HQ!- KRIN LINN